

UNCLASSIFIED

AD NUMBER	
AD047060	
CLASSIFICATION CHANGES	
TO:	unclassified
FROM:	confidential
LIMITATION CHANGES	
TO:	Approved for public release; distribution is unlimited.
FROM:	Distribution authorized to DoD only; Administrative/Operational Use; 01 AUG 1954. Other requests shall be referred to Office of Naval Research, One Liberty Center, Suite 875, 1425 North Randolph Street, Arlington, VA 22203 -1995. Pre-dates formal DoD distribution statements. Treat as DoD only.
AUTHORITY	
31 Aug 1966, DoDD 5200.10; ONR ltr dtd 13 Sep 1977	

THIS PAGE IS UNCLASSIFIED

THIS REPORT HAS BEEN DELIMITED  
AND CLEARED FOR PUBLIC RELEASE  
UNDER DOD DIRECTIVE 5200.20 AND  
NO RESTRICTIONS ARE IMPOSED UPON  
ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.

**UNCLASSIFIED**

---

---

**AD** \_\_\_\_\_

*Reproduced  
by the*

**ARMED SERVICES TECHNICAL INFORMATION AGENCY  
ARLINGTON HALL STATION  
ARLINGTON 12, VIRGINIA**



DECLASSIFIED  
DOD DIR 5200.9

---

---

**UNCLASSIFIED**

Qmc

Beau  
Yout  
will

# Services Technical Information Agency

lited supply, you are requested to return this copy WHEN IT HAS SERVED  
so that it may be made available to other requesters. Your cooperation  
ed.

AM

47060

NOTICE  
THE U  
SER  
THESE  
GOVER  
SAID D  
EMPLO  
PURPO  
USE OF

IN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA  
FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED  
PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS  
NO LIABILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE  
HOLDER MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE  
SPECS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY  
THE GOVERNMENT AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER  
CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE,  
OR ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

Reproduced by  
DOCUMENT SERVICE CENTER  
KNOTT BUILDING, DAYTON, 2, OHIO

**NOTICE: THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE**  
**NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING**  
**OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 and 794.**  
**THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN**  
**ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.**

CONFIDENTIAL

**General Mills, Inc.**  
**Mechanical Division**

MD-2

500  
MAY 1958  
2003 E. HENNEPIN AVENUE  
MINNEAPOLIS 13, MINN.

**ENGINEERING RESEARCH & DEVELOPMENT  
DEPARTMENT**

2003 EAST HENNEPIN AVENUE  
MINNEAPOLIS 13, MINN.

CONFIDENTIAL

1958

544A

71227

9-637

This document consists of 15 pages and is number 19  
of 38 copies, series B, and the following attachments  
PROGRESS REPORT <sup>ments.</sup> *appendix*

Contract No. Nonr 875(00)

Annex XII

August 1, 1954

Prepared for

The Office of Naval Research  
Washington 25, D. C.

Report No. 1327

Prepared by: F. Bartholomew

Approved by: Cledo Brunetti  
Cledo Brunetti, Director

GENERAL MILLS, INC.  
Mechanical Division  
ENGINEERING RESEARCH AND DEVELOPMENT  
2003 E. Hennepin Ave.  
Minneapolis 13, Minn.

This document has been reviewed in accordance with  
OPNAVINST 5510.17 paragraph 5. The security  
classification assigned to this document is correct.

Date: 1/2/54 K. E. Wright  
By direction of  
Chief of Naval Research (Code SW)

CONTINUED

NOV 22 1954

541A

71227

## TABLE OF CONTENTS

	<u>Page</u>
SUMMARY . . . . .	1
I. ENGINEERING STUDY . . . . .	3
A. Special Problems of Super-Pressure Balloon Construction . . . . .	3
B. Special Problems in the Construction of the Onion-Shaped Balloon . . . . .	3
C. The Radiation Problem . . . . .	4
D. Comparison of Balloon Weights Sphere to Onion . . . . .	4
II. BALLOON CONSTRUCTION . . . . .	5
A. Saran . . . . .	5
B. Polyethylene-on-Mylar . . . . .	5
C. Polyethylene Impregnated Fiberglas . . . . .	5
III. EXPERIMENTS EXECUTED . . . . .	6
A. Laboratory . . . . .	6
B. Flight . . . . .	9
IV. EXPERIMENTS PLANNED . . . . .	14
A. Laboratory . . . . .	14
B. Flight . . . . .	15
V. FINANCES . . . . .	15
APPENDIX	
PHOTOGRAPHS	
DRAWINGS	

# CONFIDENTIAL

## PROGRESS REPORT

Contract No. Monr 875(00)

Annex XII

August 1, 1954

### SUMMARY

When the preceding progress report was written for the period leading up to 1 June 1954, the following items had been accomplished.

1. The theory of the super-pressure balloon, upon which the work under this project is based, had been formulated. The problems of super-heat, and the special properties of the onion-shaped balloon, had been discussed with the balloon group at the University of Minnesota during a conference on the subject of super-pressure balloons. Material requirements for strength and elastic modulus had been derived.
2. Certain materials and combinations of materials had been chosen for investigation on the basis of their properties at room temperature, and their tensile properties at low temperature had been studied experimentally with a portable cold box enclosing the jaws of the tensile tester.
3. The program for the development and testing of a super-pressure balloon to meet the required objectives had been built around four major types of balloon design.
  - a. A nylon fabric cover containing a polyethylene or rubber bladder. Two balloons of this type, using polyethylene bladders had been built and flown. In both cases, the polyethylene bladder had failed before significant internal pressure had developed.
  - b. An onion-shaped cylinder balloon of Saran or of polyethylene-on-Mylar. One of this type of balloon constructed of polyethylene-on-Mylar had been built and flown. The balloon had ruptured near a fitting after being subjected to only slight internal pressure.
  - c. A sphere of Saran. The production of this type of balloon awaits the completion of the mobile electronic sealer which is being developed under this project.
  - d. A sphere of polyethylene impregnated fiberglass. The construction of this type of balloon awaits the production of a satisfactory bond between the polyethylene and fiberglass, a problem which is being attacked by the Beckman Company. Seals in this balloon would be ordinary lay-type heat seals of the polyethylene. Experiments with samples of polyethylene impregnated fiberglass had shown the seals to be stronger than the fabric.

CONFIDENTIAL

- 2 -

4. A measure of relative super-heat among balloon materials had been obtained by a laboratory technique using an infra-red lamp.

5. One flight on a 25 foot open appendix balloon had been made to investigate the relative upward and downward radiation during night time.

During the period 1 June to 1 August, which is the period covered by the present report, the following items have been accomplished.

1. Ten 1,800 cubic foot onion-shaped balloons of Saran have been produced by Brown and Bigelow with their electronic sealing equipment. One of these was laboratory tested and four were flown. The remaining five are on the shelf awaiting new type fittings.

The polyethylene-on-Mylar material was received and six 1,800 cubic foot onion-shaped balloons were constructed of it. One of these was laboratory tested, four were flown and the remaining balloon is on the shelf for study of dimensions actually produced, seals, etc.

Modifications in the polyethylene bladder for the polyethylene-in-nylon balloon were made on two balloons which were later flown.

The design work for the mobile electronic sealer for Saran film was completed and the assembly of the first prototype is expected during the first week of August.

CONFIDENTIAL

CONFIDENTIAL

- 3 -

I. ENGINEERING STUDY

A. Special Problems of Super-Pressure Balloon Construction

The series of flights conducted at Pierre, South Dakota, during the week 7 July to 14 July, which are reported in detail under Section III-B, emphasize the fact that the construction of a super-pressure balloon presents a problem which is different qualitatively from that of constructing an open-appendix balloon. Not only must the balloon be fabricated with the greatest of care to prevent any damage to the material or to assure that the seals are perfect, but the material itself must be hole-free to an extent heretofore not required. Although the gas permeability of the films being used is well on the safe side, calculations show that, if the areas of all the holes, from flaws or from damage, when added together, would amount to a hole which exceeds 1/32 of one inch in diameter, the super-pressure balloon of the size contemplated will fail to meet the required flight performance.

All of the balloons flown from Pierre expelled their free-lift gas, after developing only a fraction of the internal pressure for which they were designed, and descended after a short time, some times without ever reaching their theoretical ceiling. (An onion-shaped balloon may develop an internal pressure before reaching its theoretical ceiling for reasons explained on page 10 of Report no. 1312 dated 1 June 1954).

We feel confident that there are ways for manufacturing balloons which will meet the requirements as to gas tightness, and additional engineering talent has been enlisted to work on this problem. The major points of the program which they are pursuing are outlined in Section IV.

B. Special Problems in the Construction of the Onion-Shaped Balloon

The laboratory tests during which onion-shaped balloons were inflated revealed a problem involving the equal distribution of stresses around the circumference of the balloon. With the materials being used, the material thickness necessary, and the present gathering techniques, it appears that some meridional sections of material are taking greater stresses than others. This is apparent in Photographs #8125, #8131 which show quite clearly that, while some material sags between the equator and the lower fitting, other material takes a more direct line from the fitting toward the equator forming a chord connecting the outer contour of the balloon at two points. It would be expected that the material which forms the chord would be stressed more than that which billows out beyond it. Strain gages will be used to evaluate the difference in stress which is involved here.

A new fitting is being designed and a new technique for gathering the material at either end will be used in an effort to determine whether this feature is an essential part of the onion-shape or whether it is a function of the type of folding used in gathering the ends or the manner in which it is held.

CONFIDENTIAL

CONFIDENTIAL

- 4 -

The greatest care was exercised in installing the fitting to make certain that the distance from one fitting to the other along one meridian was the same for all meridians and, since the main feature of the onion-shape is an excess of material circumferentially under all conditions, some folds radiating out from the fittings must be expected. However, if the meridional stresses are to be distributed uniformly around the circumference, these folds must not be allowed to assume more than their share of the stress. Although the materials and their thicknesses, which are being used, provide a design strength which is somewhat greater than available information on super-heat indicates to be necessary, such design strengths are calculated on the assumption that the meridional stresses are uniformly distributed about the circumference. If large variations in stress are unavoidable, the onion-shaped balloon, while feasible in theory, may not prove successful with presently available materials.

By making a thorough study of all aspects of the onion-shaped balloon, we hope to answer this question conclusively.

Another feature of the onion-shaped balloon, as produced so far under this project, which may make a critical difference between the theoretical performance and the actual performance, was also revealed by the laboratory tests. In the major fold, which always develops during the inflation of an onion-shaped balloon, it was noted that the seals do not run directly from fitting to fitting; that is, they do not run in a true meridional direction, but rather they run obliquely from the fitting into the fold and out again. It was also noted that when the stresses began to develop as a result of the internal pressure, the stress lines, indicating the direction of the stress, held true to theory, being oriented vertically, that is, meridionally. Thus the condition which the onion-shaped balloon was especially designed to eliminate was actually produced; that is, the seams were subjected to transverse stresses. This condition is visible in Photograph #8133. If there is no way of eliminating these transverse stresses, the main advantage of the onion-shape is removed, and balloons which depend upon this feature, as do the polyethylene-on-Mylar balloons, which have a polyethylene seal, cannot be expected to perform in accordance with the theory.

By making a thorough study of all aspects of the onion-shape balloon, we hope to answer these questions conclusively.

#### C. The Radiation Problem

In a discussion with Dr. Barkley, it was decided that, if the radiation problem were to be studied thoroughly, the instrumentation itself would be a major project. With the balloon design and construction at its present state of development, it does not seem advisable to spend time on this project investigating the quantitative values of the effects of radiation upon a balloon which we have yet to prove feasible. This project will limit itself to delineation of the factors to be considered, an investigation of the spectra of the materials used, and suggestions of where other information might be obtained, or experiments that might be made, if deemed necessary.

#### D. Comparison of Balloon Weights Sphere to Onion

The polarized stress, which theory tells us we should obtain in an onion-shaped balloon, is bought at quite an increase in balloon weight. Calculations show that for a given material and material thickness, and a given volume, the weight of an onion-balloon exclusive of fittings will be 1.78 times the weight of a spherical balloon with the same specifications.

CONFIDENTIAL

CONFIDENTIAL

- 5 -

## II. BALLOON CONSTRUCTION

The dimensions of the onion-shaped balloons which have been made, both with Saran and with polyethylene-on-Mylar, are as follows:

Length between fittings = 23 feet  
Circumference = 663 to 683 inches.

In order to protect the material in the onion-shaped balloons from the bolt which protrudes through the fitting into the balloon, a 2 to 3 inch length of 7/8 inch I.D. tygon tubing was fastened to the inside wedge, thus surrounding the bolt as it came through the wedge and preventing contact between its edges and the material when the balloon was folded.

### A. Saran

The cylinders produced by Brown and Bigelow, using their straight bar electronic sealer on Saran film and from which we made the Saran onion balloons by gathering the ends and attaching the fittings, proved suitable so far as the sealing operation is concerned. However, the use of a straight bar sealer for this type of work, in which the material must be drawn through the machine as successive overlapping seals are made to produce one seam, is not the most efficient way to make Saran balloons. It is, of course, limited to balloons which can, like the onion or any cylinder balloon, be constructed solely of straight seals. With the mobile electronic sealer which, at this writing, is about to receive its first test, it will be possible to make Saran balloons of any desired shape. Since the Saran seal is nearly as strong as the material, the electronic sealer will be applied to the problem of making a spherical balloon of Saran, in which the serious problems mentioned above will be avoided.

### B. Polyethylene-on-Mylar

The one onion-shaped balloon of this material, which was brought back to the laboratories after the others of the same production run had been flown at Pierre, South Dakota, will be laboratory-tested and studied in an attempt to determine what modifications might be made to improve its ability to withstand internal pressure. See Section IV-A.

### C. Polyethylene Impregnated Fiberglas

On 21 July 1954, we wrote the Dobeckmun Company to inquire about the results of their work with the polyethylene impregnated fiberglas. At this writing, we have had no reply to our inquiry.

CONFIDENTIAL

CONFIDENTIAL

- 6 -

### III. EXPERIMENTS EXECUTED

#### A. Laboratory

1. The testing of the tensile properties of Saran at low temperatures has gone forward since the reinstallation of the cold box on the tensile tester. Two formulations were tested: Q853.3 and Q853.7. Three samples were broken of each formulation, for lengthwise and transverse direction, at 5°C. intervals from -40°C. to -65°C., making a total of 72 tests. The ultimate stresses recorded show a considerable scatter (Drawings A-16862-A, A-16863-A); however, most lie within a range of 14,000 to 23,000 psi. Since the weakest portion of the material determines the over-all strength, the working stress to be used cannot be over 13,000 or 14,000 psi. at the temperatures expected.

There is a curious pattern in the data for Saran Q853.3. At -55°C. and -65°C. the ultimate stress appears to be considerably greater than at the other temperatures. This could be caused by a set of non-valid tests, or possibly by a discontinuity which occurs at the point where the material fractures from cold brittleness. Evidence of this type of fracture was noticed in several of the lowest temperature tests.

Ultimate stress of the Q853.7 formulation seems to decrease gradually from a maximum at about -55°C.

2. On 21, 22, and 23 June, inflation tests of the three types of balloons, about to be flown at Pierre, South Dakota, were made.

a. The Saran A517 onion-shaped balloon was inflated with helium until buoyant equilibrium was reached. The normal flight load of 12 pounds, consisting of the exact equipment being flown for pressure telemetering, was supported by the balloon when this weigh-off was accomplished. The balloon was then inflated to fullness with nitrogen to avoid increasing the lift significantly above that experienced in flight, so that unusual stresses on the balloon at its tie-down point would not develop. Photographs taken during the inflation test of the Saran balloon are numbered 8138, 8139, 8140, 8141.

The balloon was very near its final shape when the first pressurization was noticeable. Both the pressure telemetering unit and the water manometer were connected to the line leading into the balloon and were read periodically as the pressure was increased. The data taken at that time are recorded in Table I below.

During the inflation, a large crease in the balloon extended from the top fitting down past the equator and was never completely removed. It may have contributed to the balloon's failure which occurred at that point. The crease or fold referred to consists of the excess of circumferential material which has nearly all collected at one meridian.

CONFIDENTIAL

CONFIDENTIAL

Table I

<u>Code</u>	<u>Mb.</u>	<u>Water Manometer</u>	
I(part of N)	983.0	1/8"	1/8"
N		5/8"	5/8"
NMU	983.7	3/8" x 2 =	3/4"
NMM	984.0	7/16" x 2 =	7/8"
NMN	984.5	9/16" x 2 =	1 1/8"
NMS	984.7	9/16" x 2 "	1 1/8"
NMI	985.0	$\simeq$ 5/8" x 2 =	1 1/4"

The balloon used was designed to contain 1800 cubic feet of gas. Pressurization occurred before that volume had been attained. In efforts to increase the internal pressure, it became apparent that the material was stretching, as an additional 200 cubic feet of gas were introduced without increasing the super-pressure beyond 1 1/4 inches of water. After this reading was obtained, another 20 cubic feet were introduced and, just as the new reading was about to be taken, the balloon burst. The tear was across gores near the upper fitting.

The data indicate that a 10% increase in enclosed gas was attained with only a 0.25% increase in absolute pressure. Assuming the temperature to be constant, the only conclusion to be reached is that the balloon's volume was increased. This type of behavior in plastic films is known as "creep", and it was expected that it would be encountered to some extent in Saran but not to the extent experienced here. The experiment emphasized the fact that, for the testing of Saran super-pressure balloons, either small models must be made and the values obtained must be corrected for thickness of material and temperature, or the full size balloon must be flown in order to put it in an environment where the temperature will give the material the strength which is expected of it.


b. In the inflation test of the 15 foot sphere of polyethylene, in a 15 foot spherical nylon envelope, a reefing sleeve was used in order to control the distribution of the nylon over the polyethylene during the early stages of the inflation. Negligible static build-up was experienced.

It was found that the polyethylene liner was not satisfactory as designed. Since the nylon does not act as a gas barrier, the two cells behaved as shown in the following sketch. The nylon provides no strength to support the load until the balloon is inflated well beyond that point reached on the ground before launching. As the inflation with nitrogen proceeded, it became apparent that modification to take care of two difficulties was necessary. (1) The orientation of the polyethylene with respect to the nylon at one pole of the balloon might not be the same as at the other, and hence a twist in the liner as opposed to the nylon would develop. As the

CONFIDENTIAL

CONFIDENTIAL

- 8 -




balloon reached full inflation, this could produce undesirable stresses. In order to remove this trouble, it was decided that future liners would have to be unattached to the bottom fitting and the balloon inflated through a duct, which would then be sealed and the plate fastened down. There would then be no need for a gas tightness at the fitting connections. (2) The polyethylene liner should be larger than that of the first models, that is, it should be larger than the nylon envelope which encloses it. The ones tested were already designed to be longer than the nylon envelope in the lower section near the appendix, but during the last part of the inflation, with the balloon still far from full, the polyethylene appeared to be making nearly a straight line from the outer circumference down to the appendix, and the nylon had some slack. It was decided to have later polyethylene liners made to a diameter of 17 ft.

Before the inflation was complete, a hole was found to have been torn in the polyethylene near the appendix by the incoming gas. This fault will be removed by the modification mentioned in (1) above.

The inflation technique combining the use of helium and nitrogen as described in (a) above was also used in the testing of this polyethylene in nylon balloon. See Photographs 8121, 8123.

c. An onion-shaped balloon made of polyethylene-on-Mylar was laboratory tested using the same helium-nitrogen technique. While the fittings were being put into the balloon during its manufacture, a tear was made into one gore from the opening along one seam necessary for inserting the fitting. In resealing the opening, it was therefore necessary to go around the tear with two bar seals which consequently made angles with each other and with the rest of the seam, as shown below. The balloon failed at this point after developing about 3/4 inch of water internal pressure.



CONFIDENTIAL

- 9 -

The inflation was found to be much simplified by the use of a polyethylene "reefing sleeve" made from 30 inch layflat material. However, it is doubtful that the large crease, or accumulation of folds, can be completely removed by any technique, after the reefing sleeve has been removed. Time and again, the material was distributed by hand more evenly about the crown of the balloon, but it seems to be an unstable situation. Unless all of the folds are exactly equal, an impossible situation, the material will automatically distribute itself such that the excess is all gathered in one fold. It appears that the slightest inequality in distribution causes the larger folds to gain material from the smaller ones and, in the end, the largest fold acquires all of the excess material. Photographs numbered 8127, 8132, 8134, and 8136 show the inflation test of the polyethylene-on-Mylar balloon.

#### B. Flight

The field trip to Pierre, South Dakota, where 12 balloons were flown, was planned optimistically to make certain that no data were lost due to the balloons' passing beyond the radio horizon. Since all telemetering was to be on 40 megacycles, this meant that the radio horizon was essentially the visible horizon, and we could not expect reception after the balloon had passed more than 100 to 150 miles away. It was thought necessary, therefore, to have three receiving stations to record the data from the balloons. One was located at the launching site at Pierre Municipal Airport, another at Minneapolis at the General Mills Laboratory, and a third was located in an automobile which had been especially equipped to receive the signal. The automobile was to be located on the South Dakota-Minnesota border and to move north and south on that border in accordance with instructions sent out from Pierre on 6420 kilocycles. Communications between Pierre and Minneapolis were also scheduled to be handled by radio on 6420 kilocycles. After a few flights, the mobile receiving station was returned to Minneapolis to be called out only after a balloon might prove itself capable of floating beyond the range of the receiving station at Pierre. This was never found necessary.

On each flight, the balloon was weighed-off with the greatest precision possible inside the hangar at Pierre Municipal Airport. With the exception of Flight #1206, all of the balloons were sealed after weigh-off with the intention that the free lift gas be contained.

Superheat in an onion-shaped balloon might be expected to exceed that of a spherical balloon or any other balloon in which there is no such excess of material.

#### 1. Flight #1129 (A-21322-B)

The first flight of a Saran onion-shaped balloon carrying pressure telemetering equipment was characteristic of the majority of those to follow. Launched in the early evening of the first day at Pierre, after the radio equipment and antennas had been installed, the balloon rose to an altitude which indicated that at that point it had a volume of 1490 cubic feet, and then descended gradually to the ground. The entire flight lasted only slightly more than three hours.

CONFIDENTIAL

During its ascent, the balloon commenced to pressurize at that point where its volume was approximately 1,080 cubic feet. This was at 21,000 feet MSL. The pressure telemetering instrument indicated that there it developed an internal pressure of approximately 0.25 inches of water, and that this pressure was maintained until 10 minutes after the balloon had reached its maximum altitude of 30,000 feet, at which time it had already begun its descent. Apparently this low internal pressure was sufficient to expel the free-lift gas from the balloon through some already existing hole. Since the balloon was constructed of Saran A517, which is not the formulation which is noted for its cold brittleness temperature, it is possible that flexing at the low temperature region of the atmosphere caused the balloon to develop a leak. However, the temperatures which it experienced were never below -35°C., and if the balloon had ruptured, the tear characteristics of Saran are such that it is more likely that the balloon would have split wide open and descended rapidly. Since this was not the case, the balloon having descended at approximately 270 feet per minute, it is more likely that the free-lift gas was forced out through a hole which was already in the balloon at time of launching.

2. Flight 1130 (Drawing A-21329-B)

Temperature telemetering on this flight of a 10-foot spherical balloon consisting of 1.1 ounce nylon fabric enclosing a 1.5 mil polyethylene bladder, indicated a super-heat of approximately 13°C. during a floating period of approximately 10 minutes at 32,000 feet. The data do not indicate that the temperature of the nylon and of the helium within the balloon, which appeared to be nearing equality during the floating period, ever reached the equilibrium condition before the balloon began to descend. It must be allowed, therefore, that the super-heat for a floating balloon under these conditions might be greater than that indicated on this flight. Although the load was suspended from fittings attached at the equator of the balloon and the only weight hanging at the appendix was that of the appendix ring, the balloon never attained its theoretical volume. Since a similar balloon on Flight #1177 noticeably exceeded its theoretical volume when under internal pressure, it might be assumed here that the balloon never did pressurize significantly, but was able to exhaust its free lift through a leak so easily that the spherical shape was never attained.

3. Flight #1172 (Drawing A-21326-B)

Temperature telemetering on this flight of an onion-shaped balloon of Saran Q853.3 indicates a temperature gradient in the gas within the balloon extending from the warmer temperatures near the top of the balloon to the lower temperatures near its base. Before reaching its theoretical ceiling, but after commencing to pressurize (as indicated in the data from Flight #1129), the balloon apparently split open suddenly before the temperature of the gas had reached its equilibrium condition. A maximum super-heat indicated here was 8°C. It should be noted that the type of descent experienced on Flight 1172 with a balloon constructed of Saran Q853 material is notably different from that of Flight #1129 with A517 Saran. The interpretation here would be that the balloon contained its pressure well as it continued to rise beyond the point reached by Flight #1129, and up to the point of rupture, rather than exhausting its free lift gradually through a hole which already existed.

CONFIDENTIAL

CONFIDENTIAL

- 11 -

4. Flight #1173

This flight of a polyethylene-on-Mylar onion-shaped balloon carrying a pressure telemetering equipment failed to provide any useable data. The Brailsford motor stopped running after approximately 25 minutes of operation, apparently due to the depletion of the battery power. A HAK 4 barograph carried on the flight also was of little value since the trace on a smoked disc was destroyed by smudging during handling before the barograph was returned to the laboratories.

5. Flight #1174 (Drawing A-21331-B)

Temperature telemetering on this flight of a polyethylene-on-Mylar onion-shaped balloon which floated for approximately 10 minutes at its theoretical ceiling indicates a superheat of approximately 22 degrees. In this case, the recorded data indicate that the gas within the balloon had reached its equilibrium temperature with respect to its surroundings, and that the superheat recorded would be the maximum to be expected under these conditions. The 22°C. figure is approximately one-half of the value for superheat which has been used in the design of these balloons. Since this was an onion-shaped balloon and since it did reach its theoretical ceiling, it must be assumed that the balloon was under internal pressure during its floating period; for, otherwise, its theoretical volume could not have been attained, especially with the load being suspended from its lower fitting. This would indicate that the polyethylene-on-Mylar material has promise in an onion-shaped balloon and that the trouble lies in the problem of making a balloon which is absolutely hole-free, although in this case it was not quite so pronounced as in Flight #1172 with a Saran balloon.

It is possible, of course, that the temperature readings during the floating and for a short time thereafter are in error for the gas within the balloon, as well as they were apparently in error for the free air, although the record of the gas temperature as shown is reasonable, while that of the free air would be hard to explain.

6. Flight #1175

This flight of an onion-shaped balloon constructed of Saran A517 material and carrying a pressure telemetering unit also failed to provide any data, due to the fact that the transmitter quit within 5 minutes after takeoff. Examination of the batteries in the remaining pressure telemetering units revealed some were not up to strength and these were replaced.

7. Flight #1176 (Drawing A-21330-B)

Temperature telemetering equipment flown on this spherical balloon, constructed of 2.5 ounce nylon fabric enclosing a 1.5 mil polyethylene bladder, indicated a temperature difference of approximately 13°C. between the balloon skin and free air at the maximum altitude reached. The time altitude curve indicates that the balloon burst at this point which was somewhat short of its theoretical ceiling. Since the balloon was not recovered, it is impossible at this time to determine whether or not the polyethylene bladder alone was responsible for the failure, as it was in another flight of this balloon type. The bladder in this balloon was of a diameter 2 feet larger than the enclosing nylon envelope.

CONFIDENTIAL

It is interesting to note that the temperature data obtained from the thermistors on the balloon agrees well with the flight performance, which showed the balloon to be temporarily halted in its ascent by an inversion near the ground.

8. Flight #1177 (Drawing A-21327-B)

The 1.1 ounce nylon sphere flown on this flight enclosed a bladder consisting of a 500 gram Kaysan balloon, manufactured by the Molde' Latex Products Co. of Patterson, N. J. The pressure telemetering instrument flown on this balloon indicates that, at the level where the volume of the balloon was 444 cu. ft., internal pressure commenced to develop and continued to build up until a super-pressure of 11 inches of water was reached. At this point, the balloon burst. Under this pressure, the nylon envelope stretched considerably, since the maximum altitude reached indicates a volume of nearly 100 cu. ft. more than the unstretched volume of the balloon.

Upon examination of the balloon after its return to the laboratories, it was revealed that the nylon envelope had been torn completely away from the collection ring at the point where it was attached, and the several tears had propagated up the seams nearly to the equator. The entire amount of damage to the balloon was limited to the lower hemisphere, as would be expected, since nearly the weight of the appendix ring would distort the shape in that part of the balloon making it less than a perfect sphere. The load had been suspended from loops attached at the equator of the balloon.

Of major interest in the evaluation of the type of seam used in joining the gores in the nylon envelope is the fact that none of the seams exhibited any signs of having been strained by the internal pressure, except where they had been torn as the burst section propagated. A different type of fitting at the appendix might make this type of balloon successful. It should be noted that the fact that the balloon containing the rubber bladder is the only one which withstood any significant internal pressure would seem to confirm the conclusion reached earlier that one of the major problems is that of producing an absolutely hole-free balloon.

9. Flight #1178 (Drawing A-21326-D)

The temperature telemetering equipment flown on this 2.5 ounce nylon spherical balloon containing a 1.5 mil polyethylene bladder malfunctioned so that no data on superheat were obtained. However, the altitude information was received and indicated a period of floating of 21 minutes at theoretical ceiling. The slow descent indicated that the failure of this flight was due to a leak in the balloon, and upon recovery it was discovered to consist of a fault in the seal at the crown of the balloon, which left a slit approximately 1.25 inches long at that point. It is impossible to say what type of flight this might have been had the polyethylene bladder been without this imperfection.

CONFIDENTIAL

CONFIDENTIAL

10. Flight #1179 (Drawing A-21325-B)

The data obtained from the pressure telemetering instrument flown on this onion-shaped balloon constructed of 1.5 mil polyethylene on 1 mil Mylar appears questionable. Since the balloon not only went to its ceiling but actually exceeded it, it must be assumed that it was pressurized considerably; for it is impossible to attain the true shape of an onion-shaped balloon, and thereby to attain its full volume, without pressurizing the balloon. Here, again as in Flight #1174 where a balloon of the same construction was flown and where again the balloon arose slightly above its theoretical ceiling, no burst occurred. Flight #1179 further substantiates the conclusion that the polyethylene-on-Mylar material in an onion-shaped balloon warrants further study.

11. Flight #1180 (Drawing A-21323-B)

The telemetering data obtained from this flight of an onion-shaped Saran balloon would seem to indicate that the balloon contained a hole at the time of launching since it did not reach its theoretical ceiling, and since the slow descent would not occur had the balloon burst due to its internal pressure. Here, a pressure telemetering record shows small fluctuations of the internal pressure throughout the flight, which can only be attributed to vibration of the pen arm which must have been resting on the border between two code sections.

12. Flight #1206 (Drawing A-21324-B)

Temperature telemetering equipment flown on this onion-shaped balloon of polyethylene-on-Mylar material again indicated a temperature gradient in the gas within the balloon extending from lower temperatures in the base of the balloon to warmer temperatures near the top. The superheat indicated by data from this flight amounted to a temperature difference of approximately 12°C. However, it should be noted that the free air temperature used for this comparison was that of the Weather Bureau observation at the time of the flight. The free air thermistor had been damaged during the launching.

The superheat of 12° was merely the maximum superheat attained and was at the point of bursting. It would be useful in determining the internal pressure which was developed, but it was not an indication of the superheat to be expected of this type of balloon, since the balloon had not begun to float and hence the temperature of the gas within the balloon was not that of the equilibrium condition.

Note: In the reporting of the analysis of each flight on which temperature telemetering equipment was flown, the super-pressure which was indicated by the superheat that was measured should be noted.

CONFIDENTIAL

CONFIDENTIAL

- 14 -

#### IV. EXPERIMENTS PLANNED

##### A. Laboratory

Since none of the balloon types which were originally selected for study under this project has proved successful in the form developed so far, new designs are being pursued as reported below. This does not mean, however, that the types already under study are being discarded, but rather that their performance so far has indicated that certain problems such as gas tightness are more serious than originally realized, and that designs which offer a simpler way of overcoming this difficulty should be investigated.

###### 1. Onion-shaped balloons

Onion-shaped balloons constructed of Saran and of polyethylene-on-Mylar will be subjected to further laboratory tests using modified end fittings and variations in the diameter to length ratio, in an attempt to produce a balloon which will stand the internal pressures which onion-shaped balloon theory says are possible.

###### 2. Electronic sealer for Saran film

Tests of an electronic sealer will be made to determine that its folding mechanism works properly to provide a lap seal, and to determine the proper running speed, power setting, and electrode spacing for production operation.

###### 3. Spherical Saran balloons

When the test runs for the electronic sealer mentioned above have been completed, spherical balloons of Saran will be constructed, laboratory-tested, and flown.

###### 4. Cylindrical balloons

Experiments are planned which will test several different forms of a cylindrical balloon roughly 8 ft. in diameter and 44 ft. long which would offer some advantages in overcoming the difficulties which have been encountered with the other designs. With a diameter of only 8 ft., the pressure within the balloon would develop approximately the same stress in the balloon's walls, due to the fact that it is cylindrical rather than spherical in shape. However, this design offers several distinct advantages. The design being studied is that of a cylinder each of whose ends are sealed by one transverse seam, except for one corner at which an extension of the material is formed into a small tubular appendix. The design shape for a shroud for this balloon, in which two appendices are included for instrumentation purposes, is shown in Drawing A-16819-A. Productionwise, this design has the advantage of great simplicity, and also the most troublesome feature in the production of the other types of balloons - the attachment of fittings - is completely avoided.

CONFIDENTIAL

CONFIDENTIAL

An additional advantage is found in the fact that, unlike the other balloons, the suspension of a load from one corner will not cause a distortion in the shape which would produce a weakened section. Reference here is to the fact that, in both the onion shape balloon and the spherical balloon, the weight of the appendix ring or fitting, or either of these plus the load, tends to increase the radius of curvature and consequently to increase the tensile stress in the film in that section of the balloon. In a balloon of a shape shown in Drawing A-16819-A, with the payload suspended from one corner, we are dealing with that section of the balloon whose radius of curvature is already much smaller than the major dimension, and which is not adversely affected by the suspension of the load.

The weight of such a balloon constructed of the heaviest material, Saran, would be approximately 19 lbs. and would be capable of carrying a 10-lb. payload at 42,000 ft. Four-mil polyethylene and thinner weights of polyethylene with nylon covers, or with strengthening tapes, will be tested.

#### 5. The scalloped balloon

Another suggested design is that of a polyethylene sphere reinforced by tapes running meridionally from pole to pole in such a way that the meridional stresses are taken up by the tapes, and the circumferential stresses by the polyethylene which, under pressure, billows out between the tapes with radii of curvature which are small enough to prevent the stresses from exceeding the limits of strength of the polyethylene.

#### 6. Super-pressure

Using the laboratory technique developed earlier in the project, and recorded and described in Report #1289, p. 10, superheat comparisons will be made to investigate the relative superheat to be expected from the materials actually used in the balloons developed so far under this project. Using a 1.5 mil polyethylene balloon as a control, specimens constructed of 1.5 mil polyethylene on 1 mil Mylar and of 2 mil Saran will be used in this experiment.

#### B. Flight

Additional flight experiments will be made after laboratory tests of any balloon type have gained as much information as can be gained on the ground and have indicated that the balloon type is feasible. Telemetering of altitude and either temperatures or super-pressures will be made as in past flights under this project.

#### V. FINANCES

The total of funds committed as of 31 July 1954 was \$33,377. Of this amount, \$22,574 was labor and burden. The remaining amount to \$23,068.

CONFIDENTIAL

CONFIDENTIAL

**APPENDIX**

CONFIDENTIAL

CONFIDENTIAL

PHOTOGRAPHS

Photograph  
No. \_\_\_\_\_

8121 Early stage of inflation of polyethylene-in-nylon balloon.

8123 Maximum inflation of polyethylene-in-nylon balloon before ruptured polyethylene near appendix.

8125 Fully-inflated Saran onion showing unequal distribution of meridional stresses.

8127 Attempt to distribute the slack material uniformly around the crown of a polyethylene-Mylar balloon.

8131 Fully-inflated polyethylene-Mylar onion. Some material is slack, while other portions (note straight lines from fittings) carry stress.

8132 Top view of polyethylene-Mylar onion balloon fully inflated.

8133 Polyethylene-Mylar onion pressurized to one inch of water. Note stress lines crossing seam at an angle in center of picture.

8134 Polyethylene-Mylar onion with one inch water pressure.

8136 Polyethylene-Mylar onion being inflated with reefing sleeve.

8138 Saran onion just before pressurization.

8139 Partially inflated Saran onion showing the gathering of excess material into a fold.

8140 Saran onion partially inflated.

CONFIDENTIAL

CONFIDENTIAL

DRAWINGS

Drawing  
No.

A-16819-A Mylon shroud for fully stressed cylinder balloon.

A-16862-A Breaking stress of Saran Q853.7 at low temperatures.

A-16863-A Breaking stress of Saran Q853.3 at low temperatures.

A-21322-B Time-Altitude and super-pressure curve for Flight #1129.

A-21323-B Time-Altitude and super-pressure curve for Flight #1180.

A-21324-B Time-Altitude and temperature data for Flight #1206.

A-21325-B Time-Altitude and super-pressure curve for Flight #1179.

A-21326-B Time-Altitude curve for Flight #1178.

A-21327-B Time-Altitude and super-pressure curve for Flight #1177.


A-21328-B Time-Altitude and temperature data for Flight #1172.

A-21329-B Time-Altitude and temperature data for Flight #1130.

A-21330-B Time-Altitude and temperature data for Flight #1176.

A-21331-B Time-Altitude and temperature data for Flight #1174.

CONFIDENTIAL



IF NOT SPECIFIED TOLERANCES ARE:  
±.001 - IF 3-DECIMAL FIGURES ARE GIVEN  
±.01 - IF 2-DECIMAL FIGURES ARE GIVEN  
±.1 - IF 1-DECIMAL FIGURE IS GIVEN

APP. NO.	SC. NO.	MAT.	NO. REQ'D.	NAME
APP. NO.	SC. NO.	MAT.	NO. REQ'D.	NAME
APP. NO.	SC. NO.	MAT.	NO. REQ'D.	NAME

APP. NO. 8-23-54 SC. NO. 119 MATER. SPEC. NAME BALLOON SHROUD PROJECT 8-5024

APP. NO. 8-23-54 SC. NO. 119 MATER. SPEC. NAME BALLOON SHROUD PROJECT 8-5024

APP. NO. 8-23-54 SC. NO. 119 MATER. SPEC. NAME BALLOON SHROUD PROJECT 8-5024

MINNEAPOLIS, MINN.


07/1/1951

AERONAUTICAL RESEARCH LABORATORY

**BEST AVAILABLE COPY**

15 X 10 TO THE 2 INCH  
WIRELESS TELEGRAPH  
259-11

**BREAKING STRESS OF SARAN JB53.7  
AT LOW TEMPERATURES**




GENERAL MILLS INC., ENGINEERING RESEARCH AND DEVELOPMENT DEPARTMENT, MINNEAPOLIS, MINN.

卷之三

10<sup>8</sup> TO 10<sup>10</sup> CFU/m<sup>3</sup> 359.11  
STUDY 1 (2004) 8.10.2004

BREAKING STRENGTH OF SARAN Q653.3  
AT LOW TEMPERATURES




GENERAL MILLS INC., ENGINEERING RESEARCH AND DEVELOPMENT DEPARTMENT, MINNEAPOLIS, MINNESOTA

四〇九

CONFIDENTIAL

**SUPER PRESSURE AND  
ALTITUDE DATA  
GOMI CO. 2005 DEIM BEACON NO. 11**

FLIGHT NO	4129
FLOWN	7 JULY 1954
FOR	8 3024
LOAD ON BALLOON	7.63
FREE LIFT	# = 3 K
BALLOON TYPE	
MISSION SHAPE	
D = 17.6 FT	



GENERAL HILLS INC., ENGINEERING RESEARCH AND DEVELOPMENT DEPARTMENT, MINNEAPOLIS, MINNESOTA







CONFIDENTIAL

ALTITUDE DATA  
eGMA CODE DRUM BEACON NO. 5

NO. 1 THERMISTOR	8 FT FROM TOP IN BALLOON
NO. 2 THERMISTOR	5 FT FROM TOP IN BALLOON
NO. 3 THERMISTOR	2 FT FROM TOP IN BALLOON
MEA. SUR. OBS.	FREE AIR

TEMPERATURE DATA BY AUDIO FREQUENCY  
SHIFT ON SAME BEACON USING BENDIX  
FRIEZ WHITE ROD THERMISTORS

FLIGHT NO. 1206  
FLOWN 14 JULY 1954  
FOR S 5024  
LOAD ON BALLOON 8.3K  
FREE LIFT IF = 3.51  
BALLOON TYPE MATERIAL  
SECTION SHAPE: IT MIL POLYETHYLENE  
D = 17.6 FT  
WEIGHT 200



GENERAL MILLS, INC., ENGINEERING RESEARCH AND DEVELOPMENT DEPARTMENT: MINNEAPOLIS, MINN.

CONFIDENTIAL OCT 14 1954

CONFIDENTIAL

15  
SUPER PRESSURE AND  
ALTITUDE DATA  
• GMI CODE DRUM BEACON NO. 1

10  
5  
0  
5  
10  
15  
20  
25  
30  
35  
40  
45  
50  
55  
60  
65  
70  
75  
80  
85  
90  
95  
100  
105  
110  
115  
120  
125  
130  
135  
140  
145  
150  
155  
160  
165  
170  
175  
180  
185  
190  
195  
200  
205  
210  
215  
220  
225  
230  
235  
240  
245  
250  
255  
260  
265  
270  
275  
280  
285  
290  
295  
300  
305  
310  
315  
320  
325  
330  
335  
340  
345  
350  
355  
360  
365  
370  
375  
380  
385  
390  
395  
400  
405  
410  
415  
420  
425  
430  
435  
440  
445  
450  
455  
460  
465  
470  
475  
480  
485  
490  
495  
500  
505  
510  
515  
520  
525  
530  
535  
540  
545  
550  
555  
560  
565  
570  
575  
580  
585  
590  
595  
600  
605  
610  
615  
620  
625  
630  
635  
640  
645  
650  
655  
660  
665  
670  
675  
680  
685  
690  
695  
700  
705  
710  
715  
720  
725  
730  
735  
740  
745  
750  
755  
760  
765  
770  
775  
780  
785  
790  
795  
800  
805  
810  
815  
820  
825  
830  
835  
840  
845  
850  
855  
860  
865  
870  
875  
880  
885  
890  
895  
900  
905  
910  
915  
920  
925  
930  
935  
940  
945  
950  
955  
960  
965  
970  
975  
980  
985  
990  
995  
1000  
1005  
1010  
1015  
1020  
1025  
1030  
1035  
1040  
1045  
1050  
1055  
1060  
1065  
1070  
1075  
1080  
1085  
1090  
1095  
1100  
1105  
1110  
1115  
1120  
1125  
1130  
1135  
1140  
1145  
1150  
1155  
1160  
1165  
1170  
1175  
1180  
1185  
1190  
1195  
1200  
1205  
1210  
1215  
1220  
1225  
1230  
1235  
1240  
1245  
1250  
1255  
1260  
1265  
1270  
1275  
1280  
1285  
1290  
1295  
1300  
1305  
1310  
1315  
1320  
1325  
1330  
1335  
1340  
1345  
1350  
1355  
1360  
1365  
1370  
1375  
1380  
1385  
1390  
1395  
1400  
1405  
1410  
1415  
1420  
1425  
1430  
1435  
1440  
1445  
1450  
1455  
1460  
1465  
1470  
1475  
1480  
1485  
1490  
1495  
1500  
1505  
1510  
1515  
1520  
1525  
1530  
1535  
1540  
1545  
1550  
1555  
1560  
1565  
1570  
1575  
1580  
1585  
1590  
1595  
1600  
1605  
1610  
1615  
1620  
1625  
1630  
1635  
1640  
1645  
1650  
1655  
1660  
1665  
1670  
1675  
1680  
1685  
1690  
1695  
1700  
1705  
1710  
1715  
1720  
1725  
1730  
1735  
1740  
1745  
1750  
1755  
1760  
1765  
1770  
1775  
1780  
1785  
1790  
1795  
1800  
1805  
1810  
1815  
1820  
1825  
1830  
1835  
1840  
1845  
1850  
1855  
1860  
1865  
1870  
1875  
1880  
1885  
1890  
1895  
1900  
1905  
1910  
1915  
1920  
1925  
1930  
1935  
1940  
1945  
1950  
1955  
1960  
1965  
1970  
1975  
1980  
1985  
1990  
1995  
2000  
2005  
2010  
2015  
2020  
2025  
2030  
2035  
2040  
2045  
2050  
2055  
2060  
2065  
2070  
2075  
2080  
2085  
2090  
2095  
2100  
2105  
2110  
2115  
2120  
2125  
2130  
2135  
2140  
2145  
2150  
2155  
2160  
2165  
2170  
2175  
2180  
2185  
2190  
2195  
2200  
2205  
2210  
2215  
2220  
2225  
2230  
2235  
2240  
2245  
2250  
2255  
2260  
2265  
2270  
2275  
2280  
2285  
2290  
2295  
2300  
2305  
2310  
2315  
2320  
2325  
2330  
2335  
2340  
2345  
2350  
2355  
2360  
2365  
2370  
2375  
2380  
2385  
2390  
2395  
2400  
2405  
2410  
2415  
2420  
2425  
2430  
2435  
2440  
2445  
2450  
2455  
2460  
2465  
2470  
2475  
2480  
2485  
2490  
2495  
2500  
2505  
2510  
2515  
2520  
2525  
2530  
2535  
2540  
2545  
2550  
2555  
2560  
2565  
2570  
2575  
2580  
2585  
2590  
2595  
2600  
2605  
2610  
2615  
2620  
2625  
2630  
2635  
2640  
2645  
2650  
2655  
2660  
2665  
2670  
2675  
2680  
2685  
2690  
2695  
2700  
2705  
2710  
2715  
2720  
2725  
2730  
2735  
2740  
2745  
2750  
2755  
2760  
2765  
2770  
2775  
2780  
2785  
2790  
2795  
2800  
2805  
2810  
2815  
2820  
2825  
2830  
2835  
2840  
2845  
2850  
2855  
2860  
2865  
2870  
2875  
2880  
2885  
2890  
2895  
2900  
2905  
2910  
2915  
2920  
2925  
2930  
2935  
2940  
2945  
2950  
2955  
2960  
2965  
2970  
2975  
2980  
2985  
2990  
2995  
3000  
3005  
3010  
3015  
3020  
3025  
3030  
3035  
3040  
3045  
3050  
3055  
3060  
3065  
3070  
3075  
3080  
3085  
3090  
3095  
3100  
3105  
3110  
3115  
3120  
3125  
3130  
3135  
3140  
3145  
3150  
3155  
3160  
3165  
3170  
3175  
3180  
3185  
3190  
3195  
3200  
3205  
3210  
3215  
3220  
3225  
3230  
3235  
3240  
3245  
3250  
3255  
3260  
3265  
3270  
3275  
3280  
3285  
3290  
3295  
3300  
3305  
3310  
3315  
3320  
3325  
3330  
3335  
3340  
3345  
3350  
3355  
3360  
3365  
3370  
3375  
3380  
3385  
3390  
3395  
3400  
3405  
3410  
3415  
3420  
3425  
3430  
3435  
3440  
3445  
3450  
3455  
3460  
3465  
3470  
3475  
3480  
3485  
3490  
3495  
3500  
3505  
3510  
3515  
3520  
3525  
3530  
3535  
3540  
3545  
3550  
3555  
3560  
3565  
3570  
3575  
3580  
3585  
3590  
3595  
3600  
3605  
3610  
3615  
3620  
3625  
3630  
3635  
3640  
3645  
3650  
3655  
3660  
3665  
3670  
3675  
3680  
3685  
3690  
3695  
3700  
3705  
3710  
3715  
3720  
3725  
3730  
3735  
3740  
3745  
3750  
3755  
3760  
3765  
3770  
3775  
3780  
3785  
3790  
3795  
3800  
3805  
3810  
3815  
3820  
3825  
3830  
3835  
3840  
3845  
3850  
3855  
3860  
3865  
3870  
3875  
3880  
3885  
3890  
3895  
3900  
3905  
3910  
3915  
3920  
3925  
3930  
3935  
3940  
3945  
3950  
3955  
3960  
3965  
3970  
3975  
3980  
3985  
3990  
3995  
4000  
4005  
4010  
4015  
4020  
4025  
4030  
4035  
4040  
4045  
4050  
4055  
4060  
4065  
4070  
4075  
4080  
4085  
4090  
4095  
4100  
4105  
4110  
4115  
4120  
4125  
4130  
4135  
4140  
4145  
4150  
4155  
4160  
4165  
4170  
4175  
4180  
4185  
4190  
4195  
4200  
4205  
4210  
4215  
4220  
4225  
4230  
4235  
4240  
4245  
4250  
4255  
4260  
4265  
4270  
4275  
4280  
4285  
4290  
4295  
4300  
4305  
4310  
4315  
4320  
4325  
4330  
4335  
4340  
4345  
4350  
4355  
4360  
4365  
4370  
4375  
4380  
4385  
4390  
4395  
4400  
4405  
4410  
4415  
4420  
4425  
4430  
4435  
4440  
4445  
4450  
4455  
4460  
4465  
4470  
4475  
4480  
4485  
4490  
4495  
4500  
4505  
4510  
4515  
4520  
4525  
4530  
4535  
4540  
4545  
4550  
4555  
4560  
4565  
4570  
4575  
4580  
4585  
4590  
4595  
4600  
4605  
4610  
4615  
4620  
4625  
4630  
4635  
4640  
4645  
4650  
4655  
4660  
4665  
4670  
4675  
4680  
4685  
4690  
4695  
4700  
4705  
4710  
4715  
4720  
4725  
4730  
4735  
4740  
4745  
4750  
4755  
4760  
4765  
4770  
4775  
4780  
4785  
4790  
4795  
4800  
4805  
4810  
4815  
4820  
4825  
4830  
4835  
4840  
4845  
4850  
4855  
4860  
4865  
4870  
4875  
4880  
4885  
4890  
4895  
4900  
4905  
4910  
4915  
4920  
4925  
4930  
4935  
4940  
4945  
4950  
4955  
4960  
4965  
4970  
4975  
4980  
4985  
4990  
4995  
5000  
5005  
5010  
5015  
5020  
5025  
5030  
5035  
5040  
5045  
5050  
5055  
5060  
5065  
5070  
5075  
5080  
5085  
5090  
5095  
5100  
5105  
5110  
5115  
5120  
5125  
5130  
5135  
5140  
5145  
5150  
5155  
5160  
5165  
5170  
5175  
5180  
5185  
5190  
5195  
5200  
5205  
5210  
5215  
5220  
5225  
5230  
5235  
5240  
5245  
5250  
5255  
5260  
5265  
5270  
5275  
5280  
5285  
5290  
5295  
5300  
5305  
5310  
5315  
5320  
5325  
5330  
5335  
5340  
5345  
5350  
5355  
5360  
5365  
5370  
5375  
5380  
5385  
5390  
5395  
5400  
5405  
5410  
5415  
5420  
5425  
5430  
5435  
5440  
5445  
5450  
5455  
5460  
5465  
5470  
5475  
5480  
5485  
5490  
5495  
5500  
5505  
5510  
5515  
5520  
5525  
5530  
5535  
5540  
5545  
5550  
5555  
5560  
5565  
5570  
5575  
5580  
5585  
5590  
5595  
5600  
5605  
5610  
5615  
5620  
5625  
5630  
5635  
5640  
5645  
5650  
5655  
5660  
5665  
5670  
5675  
5680  
5685  
5690  
5695  
5700  
5705  
5710  
5715  
5720  
5725  
5730  
5735  
5740  
5745  
5750  
5755  
5760  
5765  
5770  
5775  
5780  
5785  
5790  
5795  
5800  
5805  
5810  
5815  
5820  
5825  
5830  
5835  
5840  
5845  
5850  
5855  
5860  
5865  
5870  
5875  
5880  
5885  
5890  
5895  
5900  
5905  
5910  
5915  
5920  
5925  
5930  
5935  
5940  
5945  
5950  
5955  
5960  
5965  
5970  
5975  
5980  
5985  
5990  
5995  
6000  
6005  
6010  
6015  
6020  
6025  
6030  
6035  
6040  
6045  
6050  
6055  
6060  
6065  
6070  
6075  
6080  
6085  
6090  
6095  
6100  
6105  
6110  
6115  
6120  
6125  
6130  
6135  
6140  
6145  
6150  
6155  
6160  
6165  
6170  
6175  
6180  
6185  
6190  
6195  
6200  
6205  
6210  
6215  
6220  
6225  
6230  
6235  
6240  
6245  
6250  
6255  
6260  
6265  
6270  
6275  
6280  
6285  
6290  
6295  
6300  
6305  
6310  
6315  
6320  
6325  
6330  
6335  
6340  
6345  
6350  
6355  
6360  
6365  
6370  
6375  
6380  
6385  
6390  
6395  
6400  
6405  
6410  
6415  
6420  
6425  
6430  
6435  
6440  
6445  
6450  
6455  
6460  
6465  
6470  
6475  
6480  
6485  
6490  
6495  
6500  
6505  
6510  
6515  
6520  
6525  
6530  
6535  
6540  
6545  
6550  
6555  
6560  
6565

ALTITUDE DATA  
Φ ORI CODE DRUM BEACON NO. 10  
TEMPERATURE TELMETER MALFUNCTIONED

FLIGHT NO. 1178  
FLOWN 13 JULY 1954  
FOR 8 5024  
LOAD ON BALLOON 4.52 LBS.  
FREE LIFT 1# = 3.84  
BALLOON TYPE SPHERICAL  
D = 16 FT 2.5 OZ. NITON  
1.5 HELI POLYETHYLENE BLADDER  
17 FT DIA DE 2500

MAXIMUM ALTITUDE INDICATES  
VOLUME OF 1765 CUF FT

THEORETICAL CEILING  
FOR 1760 CUF FT

FREE AIR TEMPERATURE DATA

131500Z  
RADIO CITY  
NEW YORK

ALTITUDE IN FEET

10 20 30 40 50 60 70 80 90 100 110 120 130 140 150 160 170 180 190 200 210 220 230 240 250 260 270 280 290 300 310 320 330 340 350 360 370 380 390 400 410 420 430 440 450 460 470 480 490 500 510 520 530 540 550 560 570 580 590 600 610 620 630 640 650 660 670 680 690 700 710 720 730 740 750 760 770 780 790 800 810 820 830 840 850 860 870 880 890 900 910 920 930 940 950 960 970 980 990 1000

RATE OF RISE  
IN FT/MIN

502

LAUNCH SITE  
PIERRE, S. DAK.  
012.8 CST

IMPACT  
VALLEY, SD  
ESTIMATED TIME, 1:30 CST

2 3  
MN 27 JULY 1954 APPROVED

1300  
CENTRAL STANDARD TIME  
200  
ELAPSED TIME IN HOURS

GENERAL MILLS, INC., ENGINEERING RESEARCH AND DEVELOPMENT DEPARTMENT: MINNEAPOLIS, MINN.

CONTRACT NO. 131500Z 1300  
OCT 14 1954

CONFIDENTIAL


15 SUPER PRESSURE AND  
ALTITUDE DATA  
GAMI CODE: DIAW BEACON NO. 2

FLIGHT NO. 0177  
FLOWN 12 JULY 1954  
FDR 8 6024  
LOAD ON BALLOON 7.0#  
FREE LIFT - SP = 5.5  
BALLOON TYPE SPHERICAL  
D = 10 FT. 500 GRAM DAYFLIGHT MYLAR BLADDER


WEIGHT 1.1 02 NYLON ENVELOPE 6#  
D = 10 FT. 500 GRAM DAYFLIGHT MYLAR BLADDER


10  
6  
0  
-40  
-60  
-80  
-100  
-120  
-140  
-160  
-180  
-200  
-220  
-240  
-260  
-280  
-300  
-320  
-340  
-360  
-380  
-400  
-420  
-440  
-460  
-480  
-500  
-520  
-540  
-560  
-580  
-600  
-620  
-640  
-660  
-680  
-700  
-720  
-740  
-760  
-780  
-800  
-820  
-840  
-860  
-880  
-900  
-920  
-940  
-960  
-980  
-1000  
-1020  
-1040  
-1060  
-1080  
-1100  
-1120  
-1140  
-1160  
-1180  
-1200  
-1220  
-1240  
-1260  
-1280  
-1300  
-1320  
-1340  
-1360  
-1380  
-1400  
-1420  
-1440  
-1460  
-1480  
-1500  
-1520  
-1540  
-1560  
-1580  
-1600  
-1620  
-1640  
-1660  
-1680  
-1700  
-1720  
-1740  
-1760  
-1780  
-1800  
-1820  
-1840  
-1860  
-1880  
-1900  
-1920  
-1940  
-1960  
-1980  
-2000  
-2020  
-2040  
-2060  
-2080  
-2100  
-2120  
-2140  
-2160  
-2180  
-2200  
-2220  
-2240  
-2260  
-2280  
-2300  
-2320  
-2340  
-2360  
-2380  
-2400  
-2420  
-2440  
-2460  
-2480  
-2500  
-2520  
-2540  
-2560  
-2580  
-2600  
-2620  
-2640  
-2660  
-2680  
-2700  
-2720  
-2740  
-2760  
-2780  
-2800  
-2820  
-2840  
-2860  
-2880  
-2900  
-2920  
-2940  
-2960  
-2980  
-3000  
-3020  
-3040  
-3060  
-3080  
-3100  
-3120  
-3140  
-3160  
-3180  
-3200  
-3220  
-3240  
-3260  
-3280  
-3300  
-3320  
-3340  
-3360  
-3380  
-3400  
-3420  
-3440  
-3460  
-3480  
-3500  
-3520  
-3540  
-3560  
-3580  
-3600  
-3620  
-3640  
-3660  
-3680  
-3700  
-3720  
-3740  
-3760  
-3780  
-3800  
-3820  
-3840  
-3860  
-3880  
-3900  
-3920  
-3940  
-3960  
-3980  
-4000  
-4020  
-4040  
-4060  
-4080  
-4100  
-4120  
-4140  
-4160  
-4180  
-4200  
-4220  
-4240  
-4260  
-4280  
-4300  
-4320  
-4340  
-4360  
-4380  
-4400  
-4420  
-4440  
-4460  
-4480  
-4500  
-4520  
-4540  
-4560  
-4580  
-4600  
-4620  
-4640  
-4660  
-4680  
-4700  
-4720  
-4740  
-4760  
-4780  
-4800  
-4820  
-4840  
-4860  
-4880  
-4900  
-4920  
-4940  
-4960  
-4980  
-5000  
-5020  
-5040  
-5060  
-5080  
-5100  
-5120  
-5140  
-5160  
-5180  
-5200  
-5220  
-5240  
-5260  
-5280  
-5300  
-5320  
-5340  
-5360  
-5380  
-5400  
-5420  
-5440  
-5460  
-5480  
-5500  
-5520  
-5540  
-5560  
-5580  
-5600  
-5620  
-5640  
-5660  
-5680  
-5700  
-5720  
-5740  
-5760  
-5780  
-5800  
-5820  
-5840  
-5860  
-5880  
-5900  
-5920  
-5940  
-5960  
-5980  
-6000  
-6020  
-6040  
-6060  
-6080  
-6100  
-6120  
-6140  
-6160  
-6180  
-6200  
-6220  
-6240  
-6260  
-6280  
-6300  
-6320  
-6340  
-6360  
-6380  
-6400  
-6420  
-6440  
-6460  
-6480  
-6500  
-6520  
-6540  
-6560  
-6580  
-6600  
-6620  
-6640  
-6660  
-6680  
-6700  
-6720  
-6740  
-6760  
-6780  
-6800  
-6820  
-6840  
-6860  
-6880  
-6900  
-6920  
-6940  
-6960  
-6980  
-7000  
-7020  
-7040  
-7060  
-7080  
-7100  
-7120  
-7140  
-7160  
-7180  
-7200  
-7220  
-7240  
-7260  
-7280  
-7300  
-7320  
-7340  
-7360  
-7380  
-7400  
-7420  
-7440  
-7460  
-7480  
-7500  
-7520  
-7540  
-7560  
-7580  
-7600  
-7620  
-7640  
-7660  
-7680  
-7700  
-7720  
-7740  
-7760  
-7780  
-7800  
-7820  
-7840  
-7860  
-7880  
-7900  
-7920  
-7940  
-7960  
-7980  
-8000  
-8020  
-8040  
-8060  
-8080  
-8100  
-8120  
-8140  
-8160  
-8180  
-8200  
-8220  
-8240  
-8260  
-8280  
-8300  
-8320  
-8340  
-8360  
-8380  
-8400  
-8420  
-8440  
-8460  
-8480  
-8500  
-8520  
-8540  
-8560  
-8580  
-8600  
-8620  
-8640  
-8660  
-8680  
-8700  
-8720  
-8740  
-8760  
-8780  
-8800  
-8820  
-8840  
-8860  
-8880  
-8900  
-8920  
-8940  
-8960  
-8980  
-9000  
-9020  
-9040  
-9060  
-9080  
-9100  
-9120  
-9140  
-9160  
-9180  
-9200  
-9220  
-9240  
-9260  
-9280  
-9300  
-9320  
-9340  
-9360  
-9380  
-9400  
-9420  
-9440  
-9460  
-9480  
-9500  
-9520  
-9540  
-9560  
-9580  
-9600  
-9620  
-9640  
-9660  
-9680  
-9700  
-9720  
-9740  
-9760  
-9780  
-9800  
-9820  
-9840  
-9860  
-9880  
-9900  
-9920  
-9940  
-9960  
-9980  
-10000  
-10020  
-10040  
-10060  
-10080  
-10100  
-10120  
-10140  
-10160  
-10180  
-10200  
-10220  
-10240  
-10260  
-10280  
-10300  
-10320  
-10340  
-10360  
-10380  
-10400  
-10420  
-10440  
-10460  
-10480  
-10500  
-10520  
-10540  
-10560  
-10580  
-10600  
-10620  
-10640  
-10660  
-10680  
-10700  
-10720  
-10740  
-10760  
-10780  
-10800  
-10820  
-10840  
-10860  
-10880  
-10900  
-10920  
-10940  
-10960  
-10980  
-11000  
-11020  
-11040  
-11060  
-11080  
-11100  
-11120  
-11140  
-11160  
-11180  
-11200  
-11220  
-11240  
-11260  
-11280  
-11300  
-11320  
-11340  
-11360  
-11380  
-11400  
-11420  
-11440  
-11460  
-11480  
-11500  
-11520  
-11540  
-11560  
-11580  
-11600  
-11620  
-11640  
-11660  
-11680  
-11700  
-11720  
-11740  
-11760  
-11780  
-11800  
-11820  
-11840  
-11860  
-11880  
-11900  
-11920  
-11940  
-11960  
-11980  
-12000  
-12020  
-12040  
-12060  
-12080  
-12100  
-12120  
-12140  
-12160  
-12180  
-12200  
-12220  
-12240  
-12260  
-12280  
-12300  
-12320  
-12340  
-12360  
-12380  
-12400  
-12420  
-12440  
-12460  
-12480  
-12500  
-12520  
-12540  
-12560  
-12580  
-12600  
-12620  
-12640  
-12660  
-12680  
-12700  
-12720  
-12740  
-12760  
-12780  
-12800  
-12820  
-12840  
-12860  
-12880  
-12900  
-12920  
-12940  
-12960  
-12980  
-13000  
-13020  
-13040  
-13060  
-13080  
-13100  
-13120  
-13140  
-13160  
-13180  
-13200  
-13220  
-13240  
-13260  
-13280  
-13300  
-13320  
-13340  
-13360  
-13380  
-13400  
-13420  
-13440  
-13460  
-13480  
-13500  
-13520  
-13540  
-13560  
-13580  
-13600  
-13620  
-13640  
-13660  
-13680  
-13700  
-13720  
-13740  
-13760  
-13780  
-13800  
-13820  
-13840  
-13860  
-13880  
-13900  
-13920  
-13940  
-13960  
-13980  
-14000  
-14020  
-14040  
-14060  
-14080  
-14100  
-14120  
-14140  
-14160  
-14180  
-14200  
-14220  
-14240  
-14260  
-14280  
-14300  
-14320  
-14340  
-14360  
-14380  
-14400  
-14420  
-14440  
-14460  
-14480  
-14500  
-14520  
-14540  
-14560  
-14580  
-14600  
-14620  
-14640  
-14660  
-14680  
-14700  
-14720  
-14740  
-14760  
-14780  
-14800  
-14820  
-14840  
-14860  
-14880  
-14900  
-14920  
-14940  
-14960  
-14980  
-15000  
-15020  
-15040  
-15060  
-15080  
-15100  
-15120  
-15140  
-15160  
-15180  
-15200  
-15220  
-15240  
-15260  
-15280  
-15300  
-15320  
-15340  
-15360  
-15380  
-15400  
-15420  
-15440  
-15460  
-15480  
-15500  
-15520  
-15540  
-15560  
-15580  
-15600  
-15620  
-15640  
-15660  
-15680  
-15700  
-15720  
-15740  
-15760  
-15780  
-15800  
-15820  
-15840  
-15860  
-15880  
-15900  
-15920  
-15940  
-15960  
-15980  
-16000  
-16020  
-16040  
-16060  
-16080  
-16100  
-16120  
-16140  
-16160  
-16180  
-16200  
-16220  
-16240  
-16260  
-16280  
-16300  
-16320  
-16340  
-16360  
-16380  
-16400  
-16420  
-16440  
-16460  
-16480  
-16500  
-16520  
-16540  
-16560  
-16580  
-16600  
-16620  
-16640  
-16660  
-16680  
-16700  
-16720  
-16740  
-16760  
-16780  
-16800  
-16820  
-16840  
-16860  
-16880  
-16900  
-16920  
-16940  
-16960  
-16980  
-17000  
-17020  
-17040  
-17060  
-17080  
-17100  
-17120  
-17140  
-17160  
-17180  
-17200  
-17220  
-17240  
-17260  
-17280  
-17300  
-17320  
-17340  
-17360  
-17380  
-17400  
-17420  
-17440  
-17460  
-17480  
-17500  
-17520  
-17540  
-17560  
-17580  
-17600  
-17620  
-17640  
-17660  
-17680  
-17700  
-17720  
-17740  
-17760  
-17780  
-17800  
-17820  
-17840  
-17860  
-17880  
-17900  
-17920  
-17940  
-17960  
-17980  
-18000  
-18020  
-18040  
-18060  
-18080  
-18100  
-18120  
-18140  
-18160  
-18180  
-18200  
-18220  
-18240  
-18260  
-18280  
-18300  
-18320  
-18340  
-18360  
-18380  
-18400  
-18420  
-18440  
-18460  
-18480  
-18500  
-18520  
-18540  
-18560  
-18580  
-18600  
-18620  
-18640  
-18660  
-18680  
-18700  
-18720  
-18740  
-18760  
-18780  
-18800  
-18820  
-18840  
-18860  
-18880  
-18900  
-18920  
-18940  
-18960  
-18980  
-19000  
-19020  
-19040  
-19060  
-19080  
-19100  
-19120  
-19140  
-19160  
-19180  
-19200  
-19220  
-19240  
-19260  
-19280  
-19300  
-19320  
-19340  
-19360  
-19380  
-19400  
-19420  
-19440  
-19460  
-19480  
-19500  
-19520  
-19540  
-19560  
-19580  
-19600  
-19620  
-19640  
-19660  
-19680  
-19700  
-19720  
-19740  
-19760  
-19780  
-19800  
-19820  
-19840  
-19860  
-19880  
-19900  
-19920  
-19940  
-19960  
-19980  
-20000  
-20020  
-2

CONFIDENTIAL



CONFIDENTIAL






CONFIDENTIAL

OCT 14 1954

A-21330-B


GENERAL MILLS, INC., ENGINEERING RESEARCH AND DEVELOPMENT DEPARTMENT: MINNEAPOLIS, MINN.

CONFIDENTIAL





OCT 14 1954

GENERAL MILLS, INC., ENGINEERING RESEARCH AND DEVELOPMENT DEPARTMENT, MINNEAPOLIS, MINNESOTA




VAL21







#2125
















4-230





48130





#8141

# Armed Services Technical Information Agency

Because of our limited supply, you are requested to return this copy WHEN IT HAS SERVED YOUR PURPOSE so that it may be made available to other requesters. Your cooperation will be appreciated.

AD

47060

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

Reproduced by  
DOCUMENT SERVICE CENTER  
KNOTT BUILDING, DAYTON, 2, OHIO